




# ***ISO CATEGORY I (ENTRY SEMINAR)***



**Mr. James E. Berry, P.E.  
of Technical Associates of Charlotte**

## **Technical Associates Of Charlotte**

1230 West Morehead Street, Suite 400 Charlotte, N.C. 28208, U.S.A. TELEPHONE: (704) 333-9011 FAX: (704) 333-1728  
[www.technicalassociates.net](http://www.technicalassociates.net)

**SPECIALISTS IN PREDICTIVE MAINTENANCE, MACHINERY DIAGNOSTICS, AND VIBRATION REDUCTION**

## TABLE OF CONTENTS AND SEMINAR AGENDA

### (ISO CATEGORY I) ENTRY VIBRATION ANALYSIS AND PREDICTIVE MAINTENANCE TECHNIQUES

<u>SECTION</u>	<u>SUBJECT</u>	<u>PAGE</u>
<b>CHAPTER 1</b>	<b>VIBRATION MONITORING PROGRAM.....</b>	<b>1-1</b>
1.1	Introduction.....	1-1
1.2	Goal of a Vibration Monitoring Program.....	1-1
1.2.1	Continuous Monitoring Systems.....	1-1
1.2.2	Periodic Monitoring Systems.....	1-2
1.3	Vibration Monitoring and Machines with Rotating Components.....	1-4
1.4	Organizing and Implementing a Vibration Monitoring Program.....	1-6
1.4.1	Categorize and Select Machines to Include in the Vibration Program (adapted from Ref. (2)).....	1-7
1.5	Steps in a Successful Vibration Monitoring Program.....	1-9
1.5.1	Detection.....	1-9
1.5.2	Analysis.....	1-10
1.5.3	Correction.....	1-11
1.5.4	Verification.....	1-11
1.5.5	Root Cause Analysis.....	1-11
1.6	Conclusion (adapted from Ref. (2)).....	1-12
<b>CHAPTER 2</b>	<b>PRINCIPLES OF VIBRATION.....</b>	<b>2-1</b>
2.1	Introduction.....	2-1
2.2	What is Vibration?.....	2-1
2.3	Introduction to Amplitude.....	2-2
2.4	Amplitude.....	2-3
2.4.1	Displacement.....	2-3
2.4.2	Velocity.....	2-4
2.4.3	Acceleration.....	2-6
2.4.4	Benefits of Velocity.....	2-7
2.5	Spectral Amplitude Scaling - Root Mean Square (RMS), Peak and Peak-to-Peak.....	2-7
2.5.1	RMS, Peak and Peak-to-Peak Conversion and Selection.....	2-9
2.6	Description of Frequency.....	2-11
2.7	Time Waveform, Spectrum and Overall Level.....	2-12
2.7.1	General Overview.....	2-13
2.7.2	Time Waveform – Time Domain.....	2-14
2.7.3	A Cycle and the Period of Vibration.....	2-16
2.7.4	The Spectrum.....	2-17
2.7.5	What is an Overall Level and the Overall Level Trend Plot.....	2-19

<u>SECTION</u>	<u>SUBJECT</u>	<u>PAGE</u>
2.7.6	Orders .....	2-20
2.7.7	Precaution when Displaying in Orders .....	2-22
2.8	Phase Relationships.....	2-23
2.8.1	Phase from a 2-Channel Analyzer .....	2-24
2.8.2	Phase from a Strobe Light.....	2-26
2.8.3	Phase from a Tach Pulse .....	2-27
2.9	Free and Forced Vibration.....	2-28
2.10	Natural Frequency.....	2-28
2.11	Resonance .....	2-29
2.11.1	Machine Forces That Can Excite Natural Frequencies .....	2-31
2.11.2	Critical Speed.....	2-32
 <b>CHAPTER 3 DATA ACQUISITION AND SIGNAL PROCESSING.....</b>		<b>3-1</b>
3.1	Data Acquisition and Signal Processing.....	3-1
3.2	Instrumentation.....	3-1
3.3	Overall Level Meter .....	3-2
3.3.1	Definition .....	3-2
3.3.2	Benefits .....	3-2
3.3.3	Limitations .....	3-2
3.4	Portable FFT Data Collectors/Analyzers .....	3-2
3.4.1	Definition .....	3-2
3.4.2	Benefits .....	3-2
3.4.3	Limitations .....	3-3
3.5	Dynamic Range.....	3-5
3.5.1	Decibels.....	3-5
3.5.2	Noise Floor .....	3-5
3.6	Vibration Sensors .....	3-6
3.7	Types of Vibration Sensors .....	3-6
3.8	Accelerometers .....	3-7
3.8.1	Accelerometer Construction .....	3-8
3.8.2	Operation of the Compression Mode Accelerometer .....	3-9
3.8.3	Disadvantages of Compression Mode .....	3-10
3.8.4	Operation of the Shear Mode Accelerometer .....	3-11
3.8.5	Advantages of Shear Mode.....	3-11
3.9	Triaxial Accelerometers.....	3-12
3.10	Velocity sensors .....	3-12
3.10.1	Seismic Velocity Sensor.....	3-13
3.10.2	Piezoelectric Velocity Sensor .....	3-13
3.11	Non-Contacting Eddy Current Displacement Probes .....	3-14

<u>SECTION</u>	<u>SUBJECT</u>	<u>PAGE</u>
3.12	Shaft Rider Assembly .....	3-15
3.13	Sensor – Mounting Locations and Techniques .....	3-15
3.13.1	Stud Mounting .....	3-16
3.13.2	Adhesive (Epoxy) Mounting .....	3-17
3.13.3	Magnetic Mounting .....	3-17
3.13.4	Quick-Connect Mounting .....	3-18
3.13.5	Hand-Held Probes (Stingers) .....	3-18
3.14	Sensor Mounting Hardware .....	3-19
3.15	Sensor Selection Criteria .....	3-20
3.15.1	Environmental Limitations .....	3-20
3.16	Route Mode .....	3-21
3.17	Setting up a PdM Database .....	3-21
3.17.1	Machine Identification .....	3-22
3.17.2	Measurement Points .....	3-24
3.17.3	Measurement Routes .....	3-26
3.18	Downloading a Route .....	3-27
3.19	Data Collection Precautions .....	3-28
3.20	Selecting Required Instruments and Sensors .....	3-29
3.21	Safety Precautions .....	3-29
3.22	Collecting the Data .....	3-29
3.22.1	Horizontal, Vertical, and Axial Measurements .....	3-30
3.22.2	Distinguishing Valid from Invalid Data .....	3-32
3.22.3	Using an Accelerometer .....	3-34
3.22.4	Using an Extension Probe .....	3-35
3.22.5	Storing the Data .....	3-35
3.23	Uploading the Route .....	3-36
3.23.1	Connecting to the Computer .....	3-36
3.23.2	Uploading the Data .....	3-36
3.23.3	Storing the Data .....	3-37
3.24	Report Printouts .....	3-37
3.24.1	Latest Measurement Report .....	3-37
3.24.2	Exception or Overall Alarm Report .....	3-38
3.24.3	Inspection Code Report .....	3-39
3.24.4	Spectral Band Alarm Report .....	3-40
3.25	Plot Formats .....	3-42
3.25.1	Trend Plots .....	3-42
3.25.2	Narrowband Alarm Spectral Plot .....	3-44
3.25.3	Water Fall Plot .....	3-45
3.25.4	Spectrum Difference Plot .....	3-45
3.26	Off-Route/Analyzer Mode .....	3-47

<u>SECTION</u>	<u>SUBJECT</u>	<u>PAGE</u>
3.26.1	F <sub>MAX</sub> .....	3-48
3.26.2	F <sub>MIN</sub> .....	3-48
3.26.3	Lines .....	3-49
3.26.4	Frequency Span and Frequency Resolution .....	3-49
3.26.5	Auto-range (Auto-gain) .....	3-50
3.27	Frequency Definition .....	3-50
3.27.1	Frequency Expansion .....	3-50
3.28	Average Types and Number of Averages .....	3-51
3.28.1	RMS Averaging .....	3-52
3.28.2	Linear Averaging .....	3-53
3.29	Peak Hold Averaging .....	3-53
3.30	Number of Averages .....	3-54
3.31	Live-Time Measurements .....	3-54
3.32	Percent Overlap .....	3-55
3.33	Windowing .....	3-55
3.34	Sensor Selection .....	3-55
3.35	Sensitivity .....	3-56
3.36	Units .....	3-56
3.37	Spectrum Scaling .....	3-56
3.38	Data Acquisition Time .....	3-57

<b>CHAPTER 4 INTRODUCTION TO FAULT ANALYSIS USING SPECTRAL PATTERN</b>		
	<b>RECOGNITION TECHNIQUES.....</b>	<b>4-1</b>
4.1	Introduction.....	4-1
4.2	Definitions of Terminology .....	4-1
4.2.1	Subsynchronous versus Subharmonic .....	4-1
4.2.2	Synchronous versus Harmonic .....	4-3
4.2.3	Nonsynchronous .....	4-4
4.3	Modulation .....	4-5
4.3.1	Amplitude Modulation .....	4-6
4.3.2	Frequency Modulation .....	4-7
4.3.3	Is It A Beat? .....	4-9
4.4	Analyzing Machine Problems Using Vibration.....	4-11
4.4.1	Tools to Assist the Analyst .....	4-11
4.4.2	Mass Unbalance.....	4-12
4.4.3	Mass Unbalance Spectral Indications .....	4-13
4.4.4	Mass Unbalance Phase Indications .....	4-14
4.4.5	Bent Shaft.....	4-14
4.4.6	Misalignment .....	4-15

<u>SECTION</u>	<u>SUBJECT</u>	<u>PAGE</u>
4.4.7	Spectral Peaks that Indicate Resonance .....	4-19
4.4.8	Mechanical Looseness.....	4-20
4.4.9	Rolling Element Bearing Problems.....	4-21
4.4.10	Pump & Fan Problems .....	4-25
4.4.11	Gear Frequencies, Gearbox Analysis .....	4-26
4.4.12	Motors .....	4-29
4.4.13	Soft Foot.....	4-33
4.5	Conclusion.....	4-34
<b>CHAPTER 5</b>	<b>COMMON MACHINES AND RECOMMENDED LOCATIONS TO ACQUIRE VIBRATION MEASUREMENTS.....</b>	<b>5-1</b>
5.1	Introduction.....	5-1
5.2	Measurement Locations .....	5-1
5.2.1	Measurement Locations - Axial Flow Fans .....	5-2
5.2.2	Measurement Locations - Centrifugal Fans .....	5-2
5.2.3	Measurement Locations - Centrifugal Pumps .....	5-3
5.2.4	Measurement Locations - Rotary Lobe Pumps .....	5-4
5.2.5	Measurement Locations - Rotary Screw Compressors (Single Stage).....	5-4
5.2.6	Measurement Locations - Reciprocating Compressors .....	5-5
5.2.7	Measurement Locations - Centrifugal Compressors .....	5-6
<b>CHAPTER 6</b>	<b>ACQUISITION OF VIBRATION DATA FOR ACCEPTANCE TESTING .....</b>	<b>6-1</b>
6.1.1	Set up a detailed database containing specific machine name, each bearing to be measured, orientation and each measurement specification .....	6-1
6.2	Collecting Vibration Data for Acceptance Testing.....	6-5
6.3	Vibration Acceptance Testing Documentation .....	6-7
<b>CHAPTER 7</b>	<b>GLOSSARY OF COMMON VIBRATION TERMINOLOGY (COURTESY OF HEWLETT PACKARD, NOW CALLED AGILENT).....</b>	<b>7-1</b>